How to reset BAUD settings for the uBDMSX pod

Steps are:

1. Open Housing
2. Locate JB1
3. Before manipulating JB1 ensure to note the jumper block positions before
4. Move Jumper block to 0:0 postion
5. Open any terminal window and set BAUD = 9600, 8, N, 1
6. Connect serial cable to PC and POD
7. Power up POD by connecting to a target.

```
Tera Term - COM1 VT                                        _ □ ×
File   Edit   Setup   Control   Window   Help

D-Bug12 4.0.0b27
Copyright 1996 - 2004 Motorola Semiconductor
For Commands type "Help"

>bulk
>█
```

8. On the prompt type **bulk** to erase EEPROM.
9. Move jumper block to previous settings
10. Close housing.